






PLT-3X3-CT-1_5

1 OF 1

NO		NO	
01-00	 X1	02-00	 X2
NO	M10*25 bolt,nut,washer	NO	
	 X4		 X1





3X3-CT-CMN-2_5

1 OF 4

NO		NO	
03-00	 X1	12-00	 X2
NO		NO	


3X3-CT-CMN-3_5

2 OF 4

NO		NO	
06-00		04-00	
	X1		X1
NO		NO	
11-00		10-00	
	X1		X1







3X3-CT-CMN-4_5

3 OF 4

01-00	 X1	07-00	 X1
08-00	 X1	09-00	 X2
	M24*130 bolt,nut,washer  X2		M24*120 bolt,nut,washer  X2
	M16*110 bolt,nut,washer  X1		M16*105 bolt,washer  X1


3X3-CT-CMN-4_5

3 OF 4

	M12*20 bolt,washer  X6		12*75-14 bolt  X4
	M10*90 bolt,nut,washer  X1		M10*80 bolt,nut,washer  X2
	M10*40 bolt,washer  X2		M10*15 bolt,washer  X4
	M10*15 bolt  X4		φ114  X2






3X3-CT-CMN-4_5

3 OF 4

NO		NO	
	M7  X4		 X2
NO		NO	
	 X1		

3X3-CT-CMN-5_5

4 OF 4

NO		NO	
02-00	 X2	05-00	 X2
NO		NO	
	 X1		 X1
NO		NO	
	 X2		 X2