







1 OF 6

RHAM-MA



NO	Details drawing	NO	Details drawing
02-00	 × 1	04-00A	 × 1
04-00B	 × 1		 × 2

2 OF 6


NO	Details drawing	NO	Details drawing
01-00	 × 1	03-00	 × 1

2 OF 6



RHAM-MA

NO	Details drawing	NO	Details drawing
05-00	 × 2	06-00	 × 2

3 OF 6





NO	Details drawing	NO	Details drawing
12-00	 × 2		

4 OF 6


NO	Details drawing	NO	Details drawing
06-00	 × 2	07-00	 × 1

4 OF 6

RHAM-MA




NO	Details drawing	NO	Details drawing
08-00	 × 1	18-00	 × 2
	P204 bearing  × 2		M10 × 30 handle bolts  × 2
	M12 × 90 bolt,nut,washer  × 4		M12 × 85 bolt,washer  × 4
	M12 × 80 bolt,nut,washer  × 8		M12 × 75 bolt,nut,washer  × 4

RHAM-MA



NO	Details drawing	NO	Details drawing
	M12 × 35 bolt,washer  × 4		M12 × 20 bolt, washer  × 10
	M10 × 25 bolt,nut,washer  × 2		M10 × 16 bolt,big washer  × 4
	M10 × 20 hex socket bolt  × 10		M10 × 25 hex socket bolt  × 4
	M8 × 12 bolt,washer  × 6		

5 OF 6

RHAM-MA


NO	Details drawing	NO	Details drawing
14-00	 × 1		 × 1
	 × 4		

6 OF 6

NO	Details drawing	NO	Details drawing
09-00	 × 1	13-00	 × 2

6 OF 6

RHAM-MA

NO	Details drawing	NO	Details drawing
15-00	 × 1		